BUTTE COUNTY AIR QUALITY MANAGEMENT DISTRICT INSPECTION REPORT

Annual Inspection Re-inspection	Photograph(s)	20
E		
Equipment Modification	(# attached)	6
Other	X Residence	
NTC#	NTA#	
	Other NTC#	Other x

NAME OF SOURCE	Paradise Camp Fire Debris Removal							
LOCATION/PHONE:	Paradise							
CONTACT PERSON(S):	Tom Parker	TITLE:	Supervisor, Hazardous Materials Program,					
			Environmental Health Public Health Dept, Butte County					
PERMIT NUMBERS:	N/A							
EQUIPMENT:	Various mobile and portable construction equipment							
OPER SCHEDULE:	Variable							
Permission granted to inspect the facility and take pictures.								
Permit made available.								
Photograph equipment								
Complete VEE (if applicable)								
☐ Housekeeping ☐ Excellent ☐ Average ☐ Poor								
No. 14								

Findings

Additional Photos are located at O:\Photos\Enforcement\Special Projects\Paradise Burn Debris Cleanup\05-16-19

- Photo #6350 Skyway headed north. No trackout issues noted, rain soaked roadways.
- Photos #6351-6359 Billie Rd. Some recent mud and wood debris tracked onto roadway from work at home site. #6359 depicts vegetative debris burning at the southeast corner of Billie Rd and Clark, which I reported to Town of Paradise Fire.
- Photo #6362-6364 Timber/tree collection area northeast of Durham Pentz Rd and Clark Rd., minimal trackout on roadway, no dust issues. We have received complaints about dust from this facility.
 Additional gravel at entrance/exit may help with knocking off mud before trucks re-enter roadway.
- Photos #6365-6370 Weimer & Sons concrete recycling collection facility in Oroville (formerly Franklin, formerly Granite) at 4714 Pacific Heights Rd no issues
- Photos #6371-6373 Odin metal recycling facility east of 7th Avenue and north of Georgia Pacific Way in Oroville no issues

General assessment:

Rain has mitigated dust issues and washed roadways of the build-up of dirt that I have seen previously. There was minimal work being conducted; the government work was not operational the day of my inspection. I did not see any excavations. I did see mud tracked onto the roadway on side streets by private contractors. One property was observed as burning with no one in attendance and on the east side of Clark Road. I reported to Joe Tapia, CAL Fire Battalion Chief, but he wasn't too concerned. Both Granite/Weimer & Sons concrete facility and Odin metal facility looked fine. No issues.

Concerns/Issues for	Continue	inspections to	identify areas	of concer	n	
Follow-up Action:		1-0				
Investigated By:	U. Parker	Vank	Inspection Date:		5/16/19	
	Ins	pection Time	From:	13:00	To:	14:30
Report Date:	5/24/19	Reviewed B	y: WW Da	rte: 5/20	Logged:	KT 5/28/19











